	Type	#	Hits	Search Text	DBs	Time Stamp	Com ment s	Error Definition	Error
-	BRS			((gearbox or transmission) with contro with system) and (plastic with heat with (channel or passage or hole) with	with control EPO; JPO; and (plastic DERWENT; h (channel IBM_TDB	2004/07/16 16:45			0
N	B RS	2	က	((gearbox or transmission) with control with system) and (circuit with heat with (channel or passage or hole) with	with control EPO; JPO; and (circuit DERWENT; (channel lBM_TDB	2004/07/16			0
М	B R S	2	0	((gearbox or transmission) with control USPAT; Uswith system) and ((circuit EPO; JPO; adj board) with heat with CERWENT (channel or passage or IBM_TDB hole or circuit) with fluid)	with control USPAT; US-PGPUB; and ((circuit EPO; JPO; theat with DERWENT; assage or IBM_TDB	2004/07/16			0
4	BRS	7	241	((circuit adj board) with heat with (channel or passage or hole or circuit) with fluid)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/07/16			
rc	BRS	L 5	2	4 same (engine or transmission or gearbox)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/07/16		0	_
ဖ	BRS	17	25	6 not 5	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/07/16		0	

Туре	#	Type L # Hits	Search Text	DBs	Time Stamp	Gom ment	Error Definition	Error
BRS	L 6	30	4 and (engine or transmission or gearbox)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/07/16			0
BRS L111	5		(circuit adj board) with (hydraulic) with control with transmission with (casing or housing)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/07/16			0
BRS L1254	L12!		(circuit adj board) with control with transmission with (casing or housing)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/07/16			0
BRS L1318	L131		12 and (cooling or cool or heat or heating)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/07/16			0